

**FITNESS CERTIFICATE**

to be filled by the inspecting officer(Assistant engineer)

<b>Name of school</b>	<b>Carmelgiri English Medium School, Thalanji, Chungathara.</b>				
1 Name of the officer	JIMSHID P				
2 Location	Thalanji.				
3 Period for which the certificate is issued	<b>2023-24</b>				
4 Types of buildings	L	B	H	rooms	

**RCC Roof Building**

<b>Block-1</b>	Ground Floor	Class room	6.10	6.35	3.70m	4 nos
"	First Floor	Class room	6.10	6.35	3.70m	4 nos
"	Second Floor	Class room	6.10	6.35	3.70m	4 nos
		Verandah	2.40m wide in all floors			
<b>Block-2</b>	Ground Floor	Class room	6.20	6.20	3.70m	2 nos
"	Ground Floor	Class room	6.80	6.20	3.70m	1 no
"	Ground Floor	Staff room	6.80	6.20	3.70m	1 no
"	Ground Floor	Office room	6.80	6.20	3.70m	1 no
"	Ground Floor	Principal	6.80	6.20	3.70m	1 no
"	Ground Floor	Physics Lab	12.05	6.20	3.70m	1 no
"	Ground Floor	Chemistry lab	13.85	6.20	3.70m	1 no
"	First Floor	Class room	6.20	6.20	3.70m	2 nos
"	First Floor	Class room	6.80	6.20	3.70m	4 nos
"	First Floor	Biology lab	13.85	6.20	3.70m	1 no
"	First Floor	Library	13.85	6.20	3.70m	1 no
"	First Floor	Computer Lab	10.00	6.00	3.70m	1 no
"	Second Floor	Class room	6.20	6.20	3.70m	1 no
"	Second Floor	Class room	6.80	6.20	3.70m	4 nos
"	Second Floor	Class room	6.80	6.20	3.70m	4 nos
"	Second Floor	Multimedia room	10.00	6.00	3.70m	1 no
		Verandah	2.10m wide in all floors			

- 5 Nature of defects if any NIL
- a Foundation and basement NIL
- b Superstructure NIL
- c Doors and windows NIL
- d Wood work wrought and putup NIL
- e Roof NIL
- f Flooring NIL
- g Miscellaneous(cracks if any) NIL
- 6 Any major defects noticed which will render the building un safe in any manner NIL
- 7 Whether the maintenance works have been done properly YES
- 8 Whether the structure is sound or not for conducting classes. Sound for conducting classes under normal weather and wind conditions as on 27-05-2023


**Note 1:** The stability of the structure should be examined also with reference to location altitude,intensity of wind,exposure to flood etc

**Note 2:**Any additional observation deemed necessary for the certificate,may be furnished seperately with the certificate.

Note 3:Room size of classrooms didn't verified with KER. So do it before accommodating students.

Certified that the School was inspected by me on 27-05-2023.and found to be fit to conduct classes for the period for the reasons stated above.

Place:Chungathara



*L. S. G. D.*  
**ASSISTANT ENGINEER**  
 L. S. G. D. Section  
 Chungathara Grama Panchayath  
 Chungathara