

**FITNESS CERTIFICATE**

to be filled by the inspecting officer(Assistant engineer)

Name of school Carmelgiri English Medium School Thalanji, Cungathara  
 1 Name of the officer JIMSHID P  
 2 Location Thalanji  
 Period for which the certificate is issued  
 3 issued 2024-25

4	Types of buildings	L	B	H	Class rooms	
	Block-1 Ground Floor	6.10	6.35	3.70	4 nos class room	With Verandah 2.40 m wide in all floors
	" First Floor	6.10	6.35	3.70	4 nos class room	
	" Second Floor	6.10	6.35	3.70	4 nos class room	
	Block-2 Ground Floor	6.20	6.20	3.70	2 nos class room	
	" Ground Floor	6.80	6.20	3.70	1 no class room	
	" Ground Floor	6.80	6.20	3.70	1 no Staff room	
	" Ground Floor	6.80	6.20	3.70	1 no Office room	
	" Ground Floor	6.80	6.20	3.70	1 no Principal Room	
	" Ground Floor	12.05	6.20	3.70	1 no Physics Lab	
	" Ground Floor	13.85	6.20	3.70	1 no Chemistry Lab	
	" First Floor	6.20	6.20	3.70	2 nos class room	
	" First Floor	6.80	6.20	3.70	4 nos class room	
	" First Floor	13.85	6.20	3.70	1 no Biology Lab	
	" First Floor	13.85	6.20	3.70	1 no Library Room	
	" First Floor	10.00	6.00	3.70	1 no Computer Lab	
	" Second Floor	6.20	6.20	3.70	1 no class room	With Verandah 2.10 m wide in all floors
	" Second Floor	6.80	6.20	3.70	4 no class room	
	" Second Floor	6.80	6.20	3.70	4 no class room	
	" Second Floor	10.00	6.20	3.70	1 no Multimedia room	

5 Nature of defects if any NIL

a Foundation and basement NIL

b Superstructure NIL

c Doors and windows NIL

d Wood work wrought and putup NIL

e Roof NIL

f Flooring NIL

g Miscellaneous(cracks if any) NIL

Any major defects noticed which will render the building un safe in any

6 manner NIL

Whether the maintenance works  
7 have been done properly YESWhether the structure is sound or  
8 not for conducting classes. Yes, Sound for conducting classes under normal weather and wind conditions as on 21-05-2024

Note 1: The stability of the structure should be examined also with reference to location altitude, intensity of wind, exposure to flood etc

Note 2: Any additional observation deemed necessary for the certificate, may be furnished separately with the certificate.

Note 3: Room size of classrooms didn't verified with KER. So do it before accommodating students.

Certified that the School was inspected by me on 21-05-2024 and found to be fit to conduct classes for the period for the reasons stated above.



*[Signature]*  
 ASSISTANT ENGINEER  
 L. S. G. D. Section  
 Chungathara Grama Panchayath  
 Chungathara

**FITNESS CERTIFICATE**

to be filled by the inspecting officer(Assistant Executive Engineer)

- 1 Name of the officer Muhammad Ismail KT  
Assistant Executive Engineer ,  
LSGD Sub Division, Nilambur
- 2 Location Nilambur
- 3 Period for which the certificate is issued 2024-25

4 Name of School: **CARMELGIRI ENGLISH MEDIUM SCHOOL**

5 Types of buildings	L	B	H	
Ground Floor .RCC Framed structure (Building No 102/A)	57.04	15.32	3.60	1No
First Floor .RCC Framed structure (Building No 102/B)	57.04	15.32	3.60	1No
Second Floor .RCC Framed structure (Building No 102/C)	57.04	15.32	3.60	1No

- 6 Nature of defects if any Nil
- a Foundation and basement RCC
- b Superstructure LATERITE
- c Doors and windows Wood
- d Wood work wrought and putup NIL
- e Roof RCC
- f Flooring Tiles
- g Miscellaneous(cracks if any) NIL
- 7 Any major defects noticed which will render the building un safe in any manner NIL
- 8 Whether the maintenance works have been done properly New Building
- 9 Whether the structure is sound or not for conducting classes. Yes, Under normal weather and wind conditions

Note 1: The stability of the structure should be examined also with reference to location altitude,intensity of wind,exposure to flood etc

Note 2: Any additional observation deemed necessary for the certificate,may be furnished seperately with the certificate.

Certified that the School was inspected by me on 20/02/2024.and found fit for conducting classes for the period 2024-25 under normal weather conditions.

Place:Nilambur  
Date:15/04/2024



*(Signature)*  
**MUHAMMAD ISMAIL. K.T**  
PEN: 698691  
Assistant Executive Engineer  
L.S.G.D. Sub Division  
Block Panchayath, Nilambur  
Pin 679329